

COMPRESSION DEPTH ISSUE

Unfortunately, a proportion of our Annie dolls have ceased compressing the whole 5/6 cm, so please check your own manikins if you hold kit. It will be very noticeable if you have some that compress all the way, and some that don't - or if you compare your Annies to the Brayden.

We need to know how many Annies are not compressing correctly so we can purchase enough new parts, so please let us know how many you have that are working incorrectly.

If you have Annie manikins that are compressing correctly, please put a sticker on the neck so you can easily identify it. If you have kit with some manikins that are not compressing the full 5-6cm, you can suggest to people to use the defib on these instead, and practice compressions on those that are operating correctly (if you have a small enough group to do this with). If not, any compression practice is better than none - but do ask people to have a go on Brayden so you can really assess their compressions.

If your kit is from Helimed House, we are aiming to have one full compression doll in each double Annie. Please try to put them back in the bags like this (ie one with a sticker and one without).

We are actively attempting to get more funding for new kit, so hope this will not continue to long. Thanks for your patience!

